

HUB TESTING LABORATORY, INC.

Environmental Testing Service

95 Beaver Street - Waltham, MA 02453
(781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For: Mr. Roger Young
Executive Director of Business
Haverhill School District
4 Summer Street
Haverhill, MA 01830-5877

School: Crowell

Re: AHERA periodic surveillance

Scope: Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the Crowell school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 26, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimmer, Scott Smith, and Jim Brimhall.

Findings: This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.

Wet Wrap

<u>Location</u>	<u>Material</u>	<u>Comment</u>
Basement room beneath stairs (Rm. 10A)	Pipe insulation (TSI)	1½" cross-section falling out

Abatement

Library (Rm. 1)	Pipe insulation (TSI)	Damage along floor pipe
-----------------	--------------------------	-------------------------

Location


Basement Rms.
2 - 5, 9A, 10A

Material

Pipe insulation
and fittings (TSI)

Comment

Minor impaction and
deterioration



Susan Boyle
Vice President

