



HUB TESTING LABORATORY, INC.
Environmental Testing Service

95 Beaver Street - Waltham, MA 02453
(781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For: Mr. Roger Young
Executive Director of Business
Haverhill School District
4 Summer Street
Haverhill, MA 01830-5877

School: St. James


Re: AHERA periodic surveillance

Scope: Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the St. James school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 19, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimmer, Scott Smith, and Jim Brimhall.

Findings: This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.

<u>Location</u>	<u>Material</u>	<u>Comment</u>
Boiler room	Boiler jacket (TSI)	Delamination, debris
Boiler room	Tank jacket (TSI)	Water damage, debris
Rms. 1A, 1B, 2A, 2B, 2C, 4A, 6A, 6B, 8A, 9C	Rod covering in univents	Directly in flow of air exhaust

Will Look at 3/22/01


Susan Boyle
Vice President