

HUB TESTING LABORATORY, INC.

Environmental Testing Service



95 Beaver Street – Waltham, MA 02453
(781) 893-8330 (781) 893-4414 (fax)

Received 10/23/00

Report For: Mr. Ed Dufresne
L.E.A. Coordinator
Department of Inspection and Health Regulations
Haverhill, MA 01832

Site: Walnut Square Elementary School
645 Main Street
Haverhill, MA 01832

Project: Roof repair, Walnut Square Elementary School, Haverhill, MA.

Scope: This office was requested to determine if either the ceiling plaster or the wall plaster in the Walnut Square Elementary School were suspect asbestos containing materials.

Methodology: Standard procedure for performing an asbestos inspection was used. The area was surveyed and all homogeneous areas of suspect material in the impact area were identified. Any homogeneous materials that were sampled were sampled in areas that would minimize damage or be collected in areas that were inconspicuous.

Samples were collected by removing a full depth section and placing it into a zip sealed bag. All samples were labeled with distinct sample identification. All samples were returned to the laboratory and analyzed using EPA method 600/R-93/116, July 1993. Samples with distinct layers were analyzed separately as per EPA guideline.

Homogeneous Areas of Suspect Material


Hub ID #: 13046
Site: Walnut Square Elementary School
Project: Haverhill Public Schools

<u>HA #</u>	<u>Material</u>	<u>Sample</u>	<u>Friable</u> <u>Y/N</u>	<u>Cond.</u> <u>N/D/SD</u>	<u>ACM</u> <u>Y/N</u>	<u>Comment</u>
1	White Wall Plaster	133046-1	Y	N	N	

Analytical Data

<u>Sample I.D.</u>	<u>Material</u>	<u>Composition</u>	<u>%</u>
13046-1	Wall Plaster N. W. Rm. 6	Non Fibrous Mineral Chip	100
	Color: Tan		

Comments: The sample 13046 – 1 was the final sample to complete the AHERA requirement of seven samples for surfacing material over 5000 square feet. The previous six samples of this homogeneous material were non-asbestos containing. This sample was also non-asbestos containing. As per the AHERA regulation, the wall plaster in the Walnut Square Elementary School is not an Asbestos Containing Material (ACM). The ceiling plaster in Walnut Square Elementary School had been sufficiently sampled for AHERA compliance and is not ACM.



Jim G. Brimhall
Hub Testing Laboratory, Inc.
Asbestos Inspector
AI 60678