HUB TESTING LABORATORY, INC.



Environmental Testing Service

95 Beaver Street - Waltham, MA 02453 (781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For:

Mr. Roger Young

Executive Director of Business

Haverhill School District

4 Summer Street

Haverhill, MA 01830-5877

School:

Bartlett

Re:

AHERA periodic surveillance

Scope:

Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the Bartlett school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 26, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimber, Scott Smith, and Jim Brimhall.

Findings:

This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.

Remove

Location Cafeteria Material
Pipe Insulation

Comment
3 linear fe

(TSI)

3 linear feet separating from pipe and about to fall off

Wed Wrap

Location
Basement: center storage (Rm. 8), back east hall (Rm. 3E), east storage (Rm. 7)

Material
Pipe insulation
and hard fittings
(TSI)

Comment
Damage, seam separation

Susan Boyle Vice President

Bartlett

SHORT TERM WORKER

(Public Property personnel, telephone repair personnel, plumbers, heating contractors, etc.)

Name/Company	<u>Date</u>	Reason for Work	Impact on ACBM Y/N
Lyndores	1-18-01	FIX Lites	
Jim Brinway HUSTESTINGLAS	1-30-01	INSPECT	Smalles
Poblic Prop.	2/1/01	Ceiling	none
Pete Hahn Hub testing	3/1/01	6 no reinspectul	No N
J			
			·
	200200000000000000000000000000000000000		
AL			
	<u> </u>	· · · · · · · · · · · · · · · · · · ·	
1.00			

		<u>-1-1-18-0-18-0-18-0-18-0-18-0-18-0-18-0</u>	· · · · · · · · · · · · · · · · · · ·
*If your work in the building has (Designated Person) at (978) 374 Laboratories, Inc and their Certif	-2341 who will c	contact the Asbestos Consul	tant, Hub Testing