



HUB TESTING LABORATORY, INC.
Environmental Testing Service

95 Beaver Street - Waltham, MA 02453
(781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For: Mr. Roger Young
Executive Director of Business
Haverhill School District
4 Summer Street
Haverhill, MA 01830-5877

School: Consentino

Re: AHERA periodic surveillance

Scope: Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the Consentino school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 19, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimmer, Scott Smith, and Jim Brimhall.

Findings: This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.

<u>Location</u>	<u>Material</u>	<u>Comment</u>
Throughout school	Mudded pipe fittings	Minor damage on ~30%
Boiler room	Pipe insulation (TSI)	Crushed, abused
Woodshop (Rm. 160)	Aircell pipe insulation (TSI)	Exposed above wash sink
Boiler room	Tan fibrous boiler Insulation	Damage, debris on underside


Sampling →
*Teacher to be
Notified*

*Memo Regard Do Not Remove Ceiling
Tiles*

Location
Rm. 35

Material
Spray applied
fireproofing

Comment
Delaminating


Susan Boyle
Vice President

Consentino

SHORT TERM WORKER

(Telephone repair personnel, plumbers, heating contractors, etc.)

<u>Name/Company</u>	<u>Date</u>	<u>Reason for Work</u>	<u>Impact on ACBM</u>
<u>Y/N</u> HUB TESTING LAB Jim Brimhall	1-24-01	INSPECT	SAMPLING
Scott Smith	1-24-01	INSPECT	SAMPLING
George Jordan	1-31-01	Plumbing Repairs	NO
George Jordan	2-1-01	Plumbing Repairs	NO
George Jordan	2-7-01	Heat Leak	NONE
George Jordan	2-8-01	Heat Leak	NONE
Bill Prescott	2-9-1	Pneumatics	NONE
Deck Court	2-14-00	E.C.C.	
Susan Boyle	2-14-00	look @ ceiling tiles	No.
George Jordan	2-15-01	Heat Leak	NONE
George Jordan	2-20-01	water heater leak	NONE
HUB TESTING LAB Jim Brimhall	2-20-01	INSPECT	NONE
HUB Peter Hann	2-20-01	INSPECT	NONE

*If your work in the building has the potential of impacting asbestos materials contact Ed Dufresne (Designated Person) at (978) 374-2341 who will contact the Asbestos Consultant, Hub Testing Laboratories, Inc and their Certified and Massachusetts Licensed Asbestos Abatement Project Designer.