HB

HUB TESTING LABORATORY, INC.

Environmental Testing Service

95 Beaver Street - Waltham, MA 02453 (781) 893-8330 (781) 893-4414 (fax)

March 22, 2001

Report For: Mr. Ed Dufresne

LEA Designated person Electrical Inspector's Office

City Hall

4 Summer Street

Haverhill, MA

01830-5877

Hub I.D.: 13246

Project:

Crowell Elementary

Date

Received:

January 29, 2001

Scope:

This office was requested to collect bulk samples of materials that were previously identified as being a suspect asbestos containing material under the AHERA regulation. Additional samples were collected by this office to bring the total number of samples collected per homogeneous material to a minimum of three, the samples were returned to the laboratory for

analysis.

Analysis:

Analysis for the presence of asbestos was performed using Polarized

Light Microscopy EPA/600/R-93/116, July 1993.

Results:

Homogeneous Material:

Gypsum Board

A: Vinyl Layer

B: Paper Layer

C: Plaster Layer

Sample ID	Location	Composition	
13246-2-1A	Temporary Building	Cellulose	5%
		Other	95%
13246-2-1B	Temporary Building	Cellulose	100%
13246-2-1C	Temporary Building	Cellulose	10%
		Mineral Chip	90%
13246-2-2A	Temporary Building	Cellulose	5%
	·	Other	95%
13246-2-2B	Temporary Building	Cellulose	100%
13246-2-2C	Temporary Building	Cellulose	5%
		Mineral Chip	95%

Homogeneous Material:

2x2' Ceiling Tile

Sample ID	Location	Composition	
13246-2-3	Temporary Building	Cellulose	20%
٠.		Fiberglass	80%
13246-2-4	Temporary Building	Cellulose	20%
		Fiberglass	75%
	·	Mineral Chip	5%
13246-2-5	Temporary Building	Cellulose	60%
		Fiberglass	30%
		Mineral Chip	10%

Homogeneous Material:

1x1' Ceiling Tile

These tiles no longer exist in the temporary building.

The samples were received in good condition.

Comment:

In most cases two samples were collected per homogeneous material since a single sample had been collected during the original AHERA inspection.

The samples collected were not asbestos containing materials. These homogeneous materials can be removed from the suspect materials list in

the AHERA reports.

Susan Boyle Vice President

		÷	