



HUB TESTING LABORATORY, INC.

Environmental Testing Service

95 Beaver Street - Waltham, MA 02453

(781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For: Mr. Roger Young
Executive Director of Business
Haverhill School District
4 Summer Street
Haverhill, MA 01830-5877

School: Whittier

Re: AHERA periodic surveillance

Scope: Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the Whittier school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 19, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimmer, Scott Smith, and Jim Brimhall.

Findings: This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.


	<u>Location</u>	<u>Material</u>	<u>Comment</u>
<i>Abated 3/18/01</i> <i>Need Repair Work</i> <i>Need Estimate</i>	Boiler room, Boiler #2	Boiler jacket (TSI)	Repairs that are delaminating, deteriorating
	Boiler room	Breeching (TSI)	Water damage, cracks
	Boys & girls locker rooms	Pipe insulation (TSI)	Abused, delaminated, debris
	Gym (SW corner)	Pipe insulation (TSI)	Water damage, delaminating

Sample

Location
Stage left,
Boys' locker room

Material
Vibration isolator

Comment
Torn



Susan Boyle
Vice President

Whinner

SHORT TERM WORKER

(Public Property personnel, telephone repair personnel, plumbers, heating contractors, etc.)

Name/Company	Date	Reason for Work	Impact on ACBM Y/N
P/P	1/21	Problem Verification Return Pipe Boiler	
P/P	1/21	//	//
Helfrich Bros Rich Lambert	1/21	Replace 3 Boiler Tube	N
HELFRICH BROS IAN EVERTON	1/21	//	N
Jim Baumgartner Hub Testing	1/18	LEAK	N
Jim Baumgartner Hub	1/19	INSPECT	N
Scott Smith Hub	1/19	inspect	N
BM Prescott	2-7-1	Heat	N
Mike Parvate	2/12/01	Helfrich	N
Russ Harvey	2/12/01	Helfrich	N
Wally	2/20/01	KIMBALL	N
Ed O'BRIEN	2/22/01	KIMBALL	N
Jeremy Zimber	2/23/01	6 mo. Reinspection	None

*If your work in the building has the potential of impacting asbestos materials contact Ed Dufresne (Designated Person) at (978) 374-2341 who will contact the Asbestos Consultant, Hub Testing Laboratories, Inc and their Certified and Massachusetts Licensed Asbestos Abatement Project Designer.

