



HUB TESTING LABORATORY, INC.
Environmental Testing Service

95 Beaver Street - Waltham, MA 02453
(781) 893-8330 (781) 893-4414 (fax)

March 13, 2001

Report For: Mr. Roger Young
Executive Director of Business
Haverhill School District
4 Summer Street
Haverhill, MA 01830-5877

School: Tilton

Re: AHERA periodic surveillance

Scope: Under AHERA regulation, schools with asbestos containing building materials (ACBMs) must be surveyed every six months after the original inspection. During the surveillance, Hub visually inspected all assumed and known homogeneous ACBMs in the Tilton school that were detailed in the original AHERA inspection report. Hub made note of any new damage to these materials, any change in the amount of these materials, and any suspect ACBMs not included in the original report. The survey was done during the week of February 19, 2001 by Susan Boyle, Peter Hahn, Jeremy Zimmer, Scott Smith, and Jim Brimhall.

Findings: This information is noted in the attached 6 month surveillance charts, but we would like to note the following specific materials that require attention and where they are located.


*Closer Look
More Details*

<u>Location</u>	<u>Material</u>	<u>Comment</u>
Boiler Room, Boiler #1	Boiler covering	Delamination, debris on floor
Boiler Room, Boiler #2	Breeching	Cracking, significant damage
Boiler Room, Hot water tank	TSI covering	Cracked, flaking, debris
Basement boys' room custodial closet	Pipe insulation (TSI)	Damage

Location
Throughout
building

Material
Pipe insulation
and fittings (TSI)

Comment
Spot damage, cracking,
delamination



Susan Boyle
Vice President

Tilton

SHORT TERM WORKER

(Telephone repair personnel, plumbers, heating contractors, etc.)

Name/Company	Date	Reason for Work	Impact on ACBM
Kimball Mech	11-10-00	Cooller	None
Jim BRIMHALL HUB TESTING	11-10-00	10:00 AM INSPECTION	NONE
George Tom Public Paym	11-14-00	Leak	None
Bru Johnson	11/20/00		
Michael Buckley			
Kimball Mech	11-30-00	Refer Cafe	NONE
Greyhacket	11/19/01	HEAT	
Jim Bennett HUB	1/24/01	INSPECT	Sampled
SCOTT SMITH TESTING	1/24/01	INSPECT	None
Edward Kippin	1/25/01	Teintres	None
JOE Gore	1/26/01	Public priority	None
Kimball Mech	1-31-1	Heat & Ref.	None out
"	2-1-1	"	"
George Tom	2-5-01	Heat	None
LETOILE DAVE McPae	2-15-01	Roofers	2:25
LETOILE James Morgan	2,15,01	ROOF	2:25
Raymond Jones	2/20/01	Heat Pipe Abatement	YES Removal 1700 AM / 900 AM
James Howie	2/20/01	Pipe Repairs	No
Michael	2/21/01	Fire Fighter	
Joe Shinsky	2/21/01	welder	

*If your work in the building has the potential of impacting asbestos materials contact Ed Dufresne (Designated Person) at (978) 374-2341 who will contact the Asbestos Consultant, Hub Testing Laboratories, Inc and their Certified and Massachusetts Licensed Asbestos Abatement Project Designer.

Tilton

SHORT TERM WORKER

(Telephone repair personnel, plumbers, heating contractors, etc.)

Name/Company Date Reason for Work Impact on ACBM

Y/N

HAV. WATER DEPT. 2-22-01 BACK Flow NO-

R.M.S 2-23-1 16cent None

Jeremy Zimber - Hub 2/23/01 6mo. Reinspection None

Pete Aehn 2/23/01 6mo reinspection none

*If your work in the building has the potential of impacting asbestos materials contact Ed Dufresne (Designated Person) at (978) 374-2341 who will contact the Asbestos Consultant, Hub Testing Laboratories, Inc and their Certified and Massachusetts Licensed Asbestos Abatement Project Designer.