

1. Work site name and mailing address ⁹⁴⁻⁸⁶⁷ JOHN GREENLEAF WHITTIER SCHOOL 256 CENTRAL STREET HAVERHILL, MA 01830		Owner's name TOWN OF HAVERHILL	Owner's telephone No. (508) 374-2355
2. Operator's name and address VENTURE ABATEMENT SERVICES INC 50B NORTHWESTERN DR, STE#1 SALEM, NH 03079		Operator's telephone No (603) 898-6440	
3. Waste disposal site (WDS) name, mailing address, and physical site location T.R.E.E. 90 ROCHESTER NECK ROAD GONIC, NH. 03839		WDS telephone No. (800) 847-5303	
4. Name, and address of responsible agency E.P.A AGENCY U.S. EPA-REGION 1 AIR MANAGEMENT JFK FEDERAL BLDG, BOSTON, MA 02203			
5. Description of materials RQ, ASBESTOS, 9, NA2212, PG III		6. Containers No. Type	7. Total quantity 2 (cy) TWO
8. Special handling instructions and additional information			
9. OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and government regulations.			
Printed/typed name & title JOHN FEDORCHUK		Signature	Month Day Year 9-13-94
10. Transporter 1 (Acknowledgment of receipt of materials) VENTURE ABATEMENT SERVICES INC			
Printed/typed name & title JOHN FEDORCHUK		Signature <i>John Fedorchuk</i>	Month Day Year 9-13-94
Address and telephone No. 50B NORTHWESTERN DR STE #1 SALEM, NH 03079		(603)898-6440	
11. Transporter 2 (Acknowledgment of receipt of materials) N/A			
Printed/typed name & title		Signature	Month Day Year
Address and telephone No.			
12. Discrepancy indication space			
13. Waste disposal site owner or operator. Certification of receipt of asbestos materials covered by this manifest except as noted in item 12.			
Printed/typed name & title ROGER A. LIZOTTE, ASBESTOS CO-ORDINATER		Signature <i>Roger Lizotte</i>	Month Day Year 9 13 94
Waste Management Profile # 0322660		Scale Ticket # 408372	


DEC-TAM CORPORATION
10 Lowell Junction Road
ANDOVER, MASSACHUSETTS 01810
(617) 470-2860

PUBLIC PROPERTY EXPENSE
01-000-301-5200
W S S A

DATE: August 1, 1988

ASBESTOS FREE COMPANY
4 Railroad Avenue
WAKEFIELD, MASSACHUSETTS 01880
(617) 245-4403 Fax (617) 245-1892

Called 8/4/94

**VENTURE**
Asbestos
Abatement
Inc.


395 Main Street
Suite 2C
Salem, NH 03079

ROBERT J. COLETTA JR.
SENIOR ESTIMATOR

(603) 898-6440
FAX (603) 893-2776

✓
1

*John McCauley
Jeri Jordan Stone #
Asbestos Division
617-935 2160
940 8980 Waiver #
Mass DEP.*

Quality & Service
**ASBESTOS AID SPECIALISTS, INC.**

ASBESTOS REMOVAL,
ENCAPSULATION AND
DECONTAMINATION

2

DON RANDOLPH, JR.

P.O. BOX 3181
ANDOVER, MA 01810-3181
(617) 887-3028

*940 8980
Received # 8/4/94
3:15 P.M.*

SF Environmental Services, Inc.
A Division of Safelhome, Inc.

Asbestos Abatement
Mobile Surface Cleaning

3

PAUL RENNIE
617-924-9229

Corporate Office: 294 Pleasant Street, Watertown, MA 02172
Mailing Address: P.O. Box 752, Watertown, MA 02272

*Boiler Room
Condensate Return
Pump.*

136

EMS

ENVIRONMENTAL MANAGEMENT SYSTEMS INC.

8 HAYWARD STREET, ATTLEBORO, MASSACHUSETTS 02703

TELEPHONE: (508) 222-8272 or (800) 548-2893

WASTE SHIPMENT RECORD

Job Number 93-331 P.O. # _____
 Contractor VENTURE ASBESTOS ABATEMENT INC
 Address 50B NORTHWESTERN DR; [REDACTED]
 City SALEM
 State NH Zip 03079
 Telephone Number (603)898-6440
 Date Container Delivered _____
 Date of Pickup _____
 Type of Container _____
 Bag Drum Wrapped Other
 85109
 Approximate Volume of Asbestos Removed: 1845-120
ONE CUBIC YARD 120/trailer

GENERATOR/BUILDING OWNER

CITY OF HAVERHILL
CITY HALL, PURCHASING
HAVERHILL MA 01830
 City State Zip
(508)374-2355
 Phone Number

GENERATING LOCATION

GREENLEAF SCHOOL
CONCORD STREET
HAVERHILL MA 01830
 City State Zip
(508)374-2355
 Phone Number

E.P.A. AGENCY

U.S. EPA -Region 1
 Air Management - JFK Building
 Boston, MA 02203
 Phone Number (617) 565-3265

**RQ, HAZARDOUS SUBSTANCE, SOLID, O.R.M.-E
 NA9188, N,O,S (ASBESTOS)**

I hereby certify that the above named material does not contain free liquid as defined by 40 CFR part 260.10 or any applicable state law, is not hazardous waste as defined by 40 CFR part 261 or any applicable state law has been properly described, classified and packaged, and is in proper condition for transportation according to applicable regulations.

Authorized Signature [Signature]

Transporter 1. _____

I hereby certify that the above named material was picked up at the generator site listed above.

Driver: _____ License #: _____ Date: _____
 Signature

Transporter 2. E.M.S, INC

I hereby certify that the above named material was delivered without incident to the destination listed below.

Driver: [Signature] License #: 15845149 Date: 12-27-93
 Signature

Landfill Name: [REDACTED] P.S.T RECLAMATION Phone No: [REDACTED] (800)772-1862
4431 SANDS ROAD; HARWOOD, MD 20776
 Location: [REDACTED] #92-02-07-11A

Approximate Volume of Asbestos Received: _____

Discrepancy If Any: _____

I hereby certify that the above named material has been accepted and to the best of my knowledge the information provided is true and accurate..

Received by: [Signature] Date: 12/27/93



**AMERICAN ENVIRONMENTAL NETWORK
REPORT OF ASBESTOS ANALYSES BY TRANSMISSION ELECTRON MICROSCOPY (TEM)
SUMMARY OF FINDINGS PER AHERA REGULATIONS**

AEN JOB # F502-030
CLIENT: FINAL CLEARANCE ANALYSIS
CONTACT PERSON: BOB WILLIAMSON

PROJECT #: WHITTIER- RM 12-15

ANALYSES OF SAMPLES FROM WITHIN THE ABATEMENT WORK AREA INDICATE THAT AIR QUALITY REQUIREMENTS FOR COMPLETION OF ABATEMENT ACTION HAVE BEEN SATISFIED

THE MEAN FILTER LOADING IS < 18.38 ASBESTOS STRUCTURES PER MM²
(THE REGULATORY LIMIT FOR THIS ANALYSIS IS 70 STRUCTURES/MM²)

SUMMARY OF INDIVIDUAL FILTER DATA

AEN SAMPLE#	SAMPLE	S/MM ²	VOLUME
F502-030.01	1B	< 18.38	1700.00
F502-030.02	2B	< 18.38	1870.00
F502-030.03	3B	< 18.38	1870.00
F502-030.04	4B	< 18.38	1700.00
F502-030.05	5B	< 18.38	1680.00

(*----NOTE; Z-TEST CALCULATIONS USE THE VALUE OF 0.0025 FOR THOSE FILTERS WHERE NO ASBESTOS WAS OBSERVED, DENOTED BY THE "<" SIGN.)

RESPECTFULLY SUBMITTED: *[Signature]* DATE: 6/25/97

NOTE: AMERICAN ENVIRONMENT NETWORK IS NOT RESPONSIBLE FOR INCORRECT SAMPLING PROCEDURES SINCE THESE AIR SAMPLES (STRUCTURES/CC) WERE NOT COLLECTED BY OUR LAB PERSONNEL. AEN IS ONLY RESPONSIBLE FOR THE ANALYSIS AND REPORTING OF SUBMITTED SAMPLES. ACCREDITATION IN NO WAY CONSTITUTES OR IMPLIES PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY NVLAP. THIS REPORT RELATES ONLY TO THE SPECIFIC SAMPLES TESTED HEREIN.



AMERICAN ENVIRONMENTAL NETWORK
REPORT OF ASBESTOS ANALYSES BY TRANSMISSION ELECTRON MICROSCOPY (TEM)
SUMMARY OF FINDINGS PER AHERA REGULATIONS

AEN JOB # F502-031 PROJECT #: WHITTIER SCH. RM 20
CLIENT: FINAL CLEARANCE ANALYSIS, INC.
CONTACT PERSON: BOB WILLIAMSON

ANALYSES OF SAMPLES FROM WITHIN THE ABATEMENT WORK AREA INDICATE THAT AIR QUALITY REQUIREMENTS FOR COMPLETION OF ABATEMENT ACTION HAVE BEEN SATISFIED

THE MEAN FILTER LOADING IS < 15.93 ASBESTOS STRUCTURES PER MM^2 (THE REGULATORY LIMIT FOR THIS ANALYSIS IS 70 STRUCTURES/MM^2)

SUMMARY OF INDIVIDUAL FILTER DATA

AEN SAMPLE#	SAMPLE	S/MM^2	VOLUME
F502-031.01	1	< 15.32	1300.00
F502-031.02	2	< 15.32	1365.00
F502-031.03	3	< 18.38	1430.00
F502-031.04	4	< 15.32	1235.00
F502-031.05	5	< 15.32	1300.00

(*----NOTE; Z-TEST CALCULATIONS USE THE VALUE OF 0.0025 FOR THOSE FILTERS WHERE NO ASBESTOS WAS OBSERVED, DENOTED BY THE "<" SIGN.)

RESPECTFULLY SUBMITTED: Euneth T. Dohy DATE: 6.25.97

NOTE: AMERICAN ENVIRONMENT NETWORK IS NOT RESPONSIBLE FOR INCORRECT SAMPLING PROCEDURES SINCE THESE AIR SAMPLES (STRUCTURES/CC) WERE NOT COLLECTED BY OUR LAB PERSONNEL. AEN IS ONLY RESPONSIBLE FOR THE ANALYSIS AND REPORTING OF SUBMITTED SAMPLES. ACCREDITATION IN NO WAY CONSTITUTES OR IMPLIES PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY NVLAP. THIS REPORT RELATES ONLY TO THE SPECIFIC SAMPLES TESTED HEREIN.

SUMMIT TRANSPORT GROUP, INC.

P.O. BOX 1023, MORRISVILLE, PA 19067

PHONE: (215) 736-3516

№ 25007

NON-HAZARDOUS WASTE MANIFEST

S.T.G. # 122-97

GENERATOR

TRANSPORTER

DISPOSAL SITE

<p>1. Material Origin Site WHITTIER SCHOOL 256 CONCORD ST. HAVERHILL, MA 01830</p>	<p>Generator: Name/Address CITY OF HAVERHILL 4 SUMMER ST. HAVERHILL, MA 01830</p>	<p>Generator: Phone # (508) 374-2309</p>						
<p>2. Removal Contractor: Name/Address Air Quality Experts, Inc. 40 Lowell Road, Unit 1 Salem, NH 03079</p>	<p>Contact: Chris Thompson</p>	<p>Contractor: Phone # 603 894-6465</p>						
<p>3. Responsible Agency: Name/Address U.S. EPA Region I JFK Federal Building Boston, MA 02203-2211</p>	<p>4. US DOT Class - FRIABLE ASBESTOS ONLY RQ ASBESTOS, 9, NA 2212, PG III</p>							
<p>5. Description of Materials Specify Friable or Non-Friable ACM</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;">Containers No.</th> <th style="width: 40%;">Type</th> <th style="width: 30%;">Total Quantity</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">BAGS</td> <td style="text-align: center;">341</td> </tr> </tbody> </table>	Containers No.	Type	Total Quantity	7	BAGS	341	<p>6. Special Handling Instructions 24-hour emergency spill response no. 800-832-7972</p>
Containers No.	Type	Total Quantity						
7	BAGS	341						
<p>7. Generator Certification: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transport by highway according to the applicable regulations of the Department of Transportation, US E.P.A., and any other state, government agency. I certify that the foregoing is true and correct to the best of my knowledge. If the waste shipment is not as I stated, I accept the RETURN of the COMPLETE LOAD to the generator's service location at the generator's expense.</p>								
<p>Printed/Typed Name & Title CHRIS THOMPSON / PRESIDENT</p>	<p>Signature <i>Chris Thompson</i></p>	<p>Date 6/24/97</p>						
<p>8. Transporter 1 (Acknowledgement of Receipt of Materials) *If blank, Transporter 2 serves as sole transporter.</p>								
<p>Company Name & Address Hovey</p>	<p>Signature: <i>Norbert</i> Printed Name: Norbert Title:</p>	<p>Telephone No. Date: 7-2-97</p>						
<p>9. Transporter 2 (Acknowledgement of Receipt of Materials)</p>								
<p>Company Name & Address Summit Transport Group, Inc. P.O. Box 1023 Morrisville, PA 19067</p>	<p>Signature: <i>Barry Grader</i> Printed Name: Barry Grader Title:</p>	<p>Telephone No. 215 736-3516 Date: 6-24-97</p>						
<p>10. Discrepancy Indication Space:</p>								
<p>11. Waste Disposal/Recycling Site Owner or Operator's Certification (Receipt of above Waste Except as Noted in 10)</p>								
<p>Company Name & Address Southern Alleghenias Disposal Service, Inc. R.D. #3, Box 310 Apple, PA 15935</p>	<p>Signature: <i>Loren Stahl</i> Printed Name: LOREN STAHL Title:</p>	<p>Telephone No. 814 479-2537 Date: 7-2-97</p>						
<p>Site No. <u>100081</u></p>								

DEPARTMENT OF INSPECTIONAL & HEALTH REGULATIONS

City Hall, 4 Summer Street

FAX: 1-978-374-2337

Health and Environmental Division

Board of Health (978) 374-2325

(978) 374-2430



Building/Zoning Enforcement Division

Building Inspector (978) 374-2338

Gas/Plumbing (978) 374-2341

Sealer of Wgt./Measures (978) 374-2341

Wire Inspector (978) 374-2341

CITY OF HAVERHILL

MASSACHUSETTS 01830-5882

James A. Rurak

Mayor

September 23, 1998

Dr. Fritz Esch
Superintendent of Schools
Haverhill Public Schools
City Hall, Room 104

RE: 256 Concord Street
John Greenleaf Whittier School
Asbestos Related Material

Dear Dr. Esch:

On Tuesday, September 22, 1998 I met with the principal of the John Greenleaf Whittier School, Gerald Quatrane. I notified him of whom to call in the event of an incident relative to suspected asbestos contained material.

For the most part, asbestos contained material is located in the boiler room and crawl space areas. The boiler room is in relatively good condition as to stability of material installed.

I will ask Frank DiStefano to post notices at crawl space entrances advising workmen of the potential hazardous environment. I checked with the head custodian and he had no complaints about the rest of the building.

Sincerely,


E.H. Dufresne
L.E.A. Coordinator

EHD/pm

cc: Gerald Quatrane, Principal
Frank DiStefano, Director of Public Property
William Johnson, Director of Maintenance

D. Fritz Eck
Superintendent
Haverhill
Public Schools

9/22/98

Re: Asbestos Related Material
John Greenleaf Whittier School
256 Concord St.

Dear Dr. Eck,

On Tuesday September 22, 1998 I met with the principal of the John Greenleaf Whittier School. I notified him of who to call in the event of an incident relative to suspected asbestos contained materials.

For the most part, asbestos contained material is located in the boiler room and crawl space areas. The boiler room is in relatively good condition as to stability of materials installed.

I will ask Frank DiStefano to post notices at crawl space entrances advising workmen of the potential hazardous environment. I checked with the head custodian and he had no complaints about the rest of the building.

Sincerely

E. H. Lefebvre
S.E.A. Coordinator

c.c. Gerald Quatrone
Frank DiStefano
Wm. Johnson