

PERIODIC SURVEILLANCE

Form AA010

1. Building: Crowell
2. Date of Surveillance: 4/1/98
3. Name of person conducting surveillance: Frank D. Stefano  
Edward R. Caperno
4. Did you visually inspect all areas that are identified in the Management Plan as asbestos-containing building materials? yes ✓ no
5. Is there any change in the condition of these materials since the last periodic surveillance? yes     no ✓

Comments: Condensate return pipe in cellar left side  
needs inspection. Should be inspected to prevent  
abrasion of pipe wrap.  
All others appear in good condition